

Super Strip

No Rinse Stripper

Removedor que no
Necesita Enjuagarse

Super Strip

Technical Data

Description

This time and labor saving stripper works by breaking the molecular "film forming" bond of floor finishes and waxes. It "re-emulsifies" all but the heaviest finish buildups with or without scrubbing. This allows the stripper to be applied by mop and picked up by mop and bucket or wet vac. Any remaining solution evaporates completely eliminating the need to rinse before recoating. Unlike ordinary strippers, no alkali film is left behind to prevent bonding of new finish to the floor.

Where to Use

- Hospitals, nursing homes, doctors offices
- Schools, universities, child care centers
- Malls, retail stores, grocery stores

Specifications

Available Sizes 4/1 gal. or 5 gal.
 Physical State Liquid
 Color Clear
 Fragrance Sassafras
 Foaming Low
 Free Rinsing Yes
 Petroleum Distillates None
 Viscosity Thin
 Specific Gravity 1.070
 pH (undiluted) 13

What the Pros Know

When stripping finished floors, only apply enough solution to keep the area you are working on wet. Avoid having areas where stripper has been applied starting to dry. This makes the finish removal task much more difficult.

- Concentrated Economical
- Fast Acting Labor Saving
- Completely Rinse Free Labor Saving
- Removes Many Types of Finish
 Ease of use
 Low Odor Pleasant to Use

This product is designed for use in conjunction with a mechanical stripping program. Best results will be achieved when used with the proper stripping pad and 175 rpm machine. It is designed as a no rinse formula, eliminating the need for flood rinsing saving you time and money.

Directions



Wear safety equipment recommended on MSDS, read all directions and cautions prior to beginning your work.



Medium buildup dilute 1:5 (25 ounces per gallon of water). For heavy buildup dilute 1:3 (42 ounces per gallon of water).



Apply solution at rate of 150-300 square feet per gallon. Apply enough material to ensure complete wetting.



Allow to stand 5-10 minutes minimum. **DO NOT ALLOW SOLUTION TO DRY.** Re-wet as needed.



Scrub floor with floor machine using a proper stripping pad to break softened film. Flip pad and replace as needed.



Pick up solution with wet vac or automatic scrubber, if not available, use damp mop for pick-up. If mop is used for pick-up, use extreme care to remove all residue and change water frequently.



Damp mop with clean, cool water to remove all residues, and allow to dry before applying finish.

Low Odor

Fast Acting

Completely Rinse Free



020308-745

Phone: 800-262-7104
 Fax: 800-423-6254